



## Mayers' House Remains

**Date**

1973

**Primary Maker**

Phillips, H.B.

**Medium**

Print

### Description

Black and white photo of the remains of Mayers' house. S.W corner. Able to see local hand-made materials used in the construction. Studs were made from small poles. Shakes used as siding and shingles were all hand-cut.

### Dimensions

8.9 × 12.6 cm (3 1/2 × 4 15/16 in.)